

ALL SALES AND SERVICE ENGINEERS SAFETY PASSPORT APPROVED



Nigel Allen



David Wadsworth



Neil Dawson



Martin Carroll



Rob Whelan



Martin Gavan



Roger Hicks








Chris Reece



Jon Bawden

SERVICE ENGINEERS FIRST AID TRAINED

<p>Health and Safety Management in Quarries: Module 8 Quarries Regulations require the operator to have A HEALTH AND SAFETY DOCUMENT</p> <ul style="list-style-type: none"> - Management Structure; - Responsibilities and Rules / Procedures for Safe Working; - Includes all Risk Assessments; Vehicle rules; Inspection, Maintenance, Testing Schemes; Shot firing Rules; Excavation and Tip rules; Health and Surveillance Arrangements; Emergency Procedures and Safety Drills. - All Equipment to be checked before use; Faces above working Places and Roads to INSPECTED before work starts. <p>VEHICLE SAFETY Quarry Vehicles Large, Un-maneuvrable and if loaded, have increased stopping distances. - Many have large Blind spots, particularly when reversing.</p>  <p>PARK Only in designated areas - Never under Quarry Face or Near Edge - use Flashing Light or Dipped Head Lights.</p> <p>QUARRY HAZARDS Falling rocks; Falls from Height; Falling Objects; Falls from Vehicles; Quicksand type Material and Working Excavations / Trenches - Must Keep Vehicles Well Clear!</p>   <p>BLASTING Sentries posted, Audible alarm and All clear, Danger Area Marked - KEEP OUT! TRANSPORT KILLS - CAN YOU SEE THE DRIVER AND CAN HE SEE YOU?</p> <p style="text-align: center;">9</p>	<p>Health and Safety Management in Quarries: Module 8</p> <p>BITUMEN Dry Powder Extinguisher to hand; No Smoking and No Naked Flame; Permit to Work and PPE required - Burns immerse in water for 10 mins, get medical help.</p> <p>RAIL LINES Permit and High Visibility clothing required; Never work between or under wagons, or cross line. Be Aware of Overhead Power Lines</p> <p>DOCKS Wear Life Jacket - Rescue facilities Available</p> <p>HAZARDOUS OPERATIONS</p> <ul style="list-style-type: none"> - Process Machinery: Stone Crusher, Conveyors, Packing Lines, Clay Presses, Ovens. - Clearing Blockages is High Risk, as is Maintenance of machinery, Electrical Systems, Services, Pressure systems and Hot Work. All Dangerous Parts to be adequately guarded. Never Remove Guards / Make Adjustments without first isolating power supply and Locking it OFF. - Permit to work issued to ensure safe equipment safe. - No Job complete until guards in place and permit cancelled; only then can power be restored.   <p>HEALTH RISKS Use of Chemicals (COSHH Assessments) - But also Dusts; Wells Disease; Dermatitis; Noise, Vibration and Heat Exhaustion.</p> <p>Eliminate Hazard / Reduce Exposure / Isolate Hazards / Control Exposure by Engineering Methods / Last Resort PPE</p> <p>ACCIDENT PREVENTION IS GOOD BUSINESS IN ANY WORK</p> <p style="text-align: center;">10</p>
--	---